

Sacramento County Office of Education

2023-24 Williams Site Review Summary

District: Robla School District
School Site: Bell Avenue Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/11/23
Number of Areas Evaluated: 12

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2023-24 Williams Site Review Summary

District: Robla School District

School Site: Robla Elementary

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/11/23

Number of Areas Evaluated: 17

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.