

## **Sacramento County Office of Education 2023-24 Williams Site Review Summary**

District: Center Joint Unified School District

School Site: Arthur S. Dudley Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/16/23

Number of Areas Evaluated: 14

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2023-24 Williams Site Review Summary**

District: Center Joint Unified School District

School Site: Oak Hill Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/16/23

Number of Areas Evaluated: 15

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2023-24 Williams Site Review Summary**

District: Center Joint Unified School District

School Site: Wilson C. Riles Middle

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/28/23

Number of Areas Evaluated: 28

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.