Sacramento County Office of Education 2023-24 Williams Site Review Summary

District: River Delta Joint Unified School District

School Site: Riverview Middle

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 9/1/23

Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

^{*} Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.