

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District  
School Site: Charles E. Mack Elementary School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/25/22

Number of Areas Evaluated: 31

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: Cosumnes Oaks High

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 9/13/22

Number of Areas Evaluated: 43

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District  
School Site: David Reese Elementary School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 7/25/22

Number of Areas Evaluated: 32

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: Franklin High

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/31/22

Number of Areas Evaluated: 42

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: Herman Leimbach Elementary School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 9/8/22

Number of Areas Evaluated: 29

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District  
School Site: Isabelle Jackson Elementary School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 7/28/22

Number of Areas Evaluated: 26

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District  
School Site: James A. McKee Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/18/22

Number of Areas Evaluated: 27

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: James Rutter Middle School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 9/27/22

Number of Areas Evaluated: 30

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.



## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: John Reith Elementary School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/22/22

Number of Areas Evaluated: 27

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: Joseph Kerr Middle

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 9/21/22

Number of Areas Evaluated: 29

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District  
School Site: Mary Tsukamoto Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/2/22

Number of Areas Evaluated: 27

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: Prairie Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 7/27/22

Number of Areas Evaluated: 25

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: Robert J. Fite Elementary

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 9/8/22

Number of Areas Evaluated: 29

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District  
School Site: Samuel Jackman Middle School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 9/16/22

Number of Areas Evaluated: 29

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: Samuel Kennedy Elementary School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 7/25/22

Number of Areas Evaluated: 19

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District

School Site: Sierra Enterprise Elementary School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/19/22

Number of Areas Evaluated: 33

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.



## **Sacramento County Office of Education 2022-23 Williams Site Review Summary**

District: Elk Grove Unified School District  
School Site: Union House Elementary School

### **Instructional Materials Site Review**

Result: Sufficient

### **School Facility Inspection Review**

Inspection Date: 8/25/22

Number of Areas Evaluated: 29

#### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

#### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.