

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: A. M. Winn Waldorf-Inspired K-8

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/13/2024

Number of Areas Evaluated: 23

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Abraham Lincoln Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/29/2024

Number of Areas Evaluated: 19

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: Aspire Capitol Heights Academy

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/12/2024

Number of Areas Evaluated: 16

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Bret Harte Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/5/2024

Number of Areas Evaluated: 20

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: California Middle

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/5/2024

Number of Areas Evaluated: 17

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Capitol Collegiate Academy

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/18/2024

Number of Areas Evaluated: 21

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: Caroline Wenzel Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/3/2024

Number of Areas Evaluated: 17

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: Cesar E. Chavez Intermediate

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/4/2024

Number of Areas Evaluated: 14

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.



# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Ethel I. Baker Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/12/2024

Number of Areas Evaluated: 21

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Fair

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Fern Bacon Middle

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/11/2024

Number of Areas Evaluated: 27

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: Hiram W. Johnson High

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/20/2024

Number of Areas Evaluated: 56

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Isador Cohen Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/29/2024

Number of Areas Evaluated: 18

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: John Bidwell Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/3/2024

Number of Areas Evaluated: 10

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: John Cabrillo Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/11/2024

Number of Areas Evaluated: 21

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: John D. Sloat Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/26/2024

Number of Areas Evaluated: 13

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Leataata Floyd Elementary

## Instructional Materials Site Review

Result: Sufficient

## School Facility Inspection Review

Inspection Date: 9/5/2024

Number of Areas Evaluated: 12

### Category Ranking\*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.



# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: Mark Twain Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/6/2024

Number of Areas Evaluated: 15

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Martin Luther King Jr. K-8

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/17/2024

Number of Areas Evaluated: 21

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Pacific Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/29/2024

Number of Areas Evaluated: 18

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Fair

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: Parkway Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/29/2024

Number of Areas Evaluated: 19

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: Rosa Parks K-8

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/16/2024

Number of Areas Evaluated: 29

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Sacramento City Unified School District

School Site: Sacramento Charter High

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/19/2024

Number of Areas Evaluated: 19

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Sam Brannan Middle

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/9/2024

Number of Areas Evaluated: 19

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: St. HOPE Public 7 Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/19/2024

Number of Areas Evaluated: 14

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.



# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: St. HOPE Public 7 Middle

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/19/2024

Number of Areas Evaluated: 19

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Suy:U Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/6/2024

Number of Areas Evaluated: 21

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Theodore Judah Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/30/2024

Number of Areas Evaluated: 25

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Poor

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Umoja International Academy

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/10/2024

Number of Areas Evaluated: 17

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Will C. Wood Middle

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 9/16/2024

Number of Areas Evaluated: 28

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Woodbine Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/26/2024

Number of Areas Evaluated: 17

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Sacramento City Unified School District

School Site: Yav Pem Suab Academy

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/14/2024

Number of Areas Evaluated: 17

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.