

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Folsom Cordova Unified School District

School Site: Cordova Gardens Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/23/2024

Number of Areas Evaluated: 18

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Folsom Cordova Unified School District

School Site: Cordova High

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/28/2024

Number of Areas Evaluated: 60

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Folsom Cordova Unified School District

School Site: Cordova Meadows Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/23/2024

Number of Areas Evaluated: 17

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Folsom Cordova Unified School District

School Site: Mills Middle

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/27/2024

Number of Areas Evaluated: 31

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Folsom Cordova Unified School District

School Site: Navigator Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/23/2024

Number of Areas Evaluated: 20

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Folsom Cordova Unified School District

School Site: Rancho Cordova Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/20/2024

Number of Areas Evaluated: 23

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Folsom Cordova Unified School District

School Site: W.E. Mitchell Middle

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/26/2024

Number of Areas Evaluated: 34

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# Sacramento County Office of Education 2024-25 Williams Site Review Summary

District: Folsom Cordova Unified School District  
School Site: Walnutwood High (Independent Study)

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/28/2024  
Number of Areas Evaluated: 5

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.



# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Folsom Cordova Unified School District

School Site: White Rock Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/20/2024

Number of Areas Evaluated: 20

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

# **Sacramento County Office of Education 2024-25 Williams Site Review Summary**

District: Folsom Cordova Unified School District

School Site: Williamson Elementary

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 8/20/2024

Number of Areas Evaluated: 21

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.